

Unable to parse fault information for: Vertical Headlight Aim Control (LRA)

Unable to parse fault information for: Radio (RAD)

## Short Test

### Siemens EMS2K Engine for Mini

No Faults Found



### Dynamic stability control DXC8 Plus - E90

Current Fault Codes



#### 0101:

Error will not cause a warning light  
Error is not currently present  
Test conditions have been completed



#### 0801:

Error will not cause a warning light  
Error is currently present  
Test conditions have not been completed  
Timeout

### Steering angle sensor (LEW/LWS)

Current Fault Codes



### Electro-hydraulic power steering R50

No Faults Found



### Multiple restraint system 4

Current Fault Codes



### Vertical headlight aim control

Radio (RAD)

The following modules were not found in the vehicle



- Electronic immobilise system 3 (EWS)
- Instrument cluster (IKE/IKI/KOMBI)
- Central body electronics (BC)
- Rain / Light sensor (RLS)
- Sunroof module (SHD)
- Seat occupancy recognition - US (OC)

This document was created with Win2PDF available at <http://www.win2pdf.com>.  
The unregistered version of Win2PDF is for evaluation or non-commercial use only.  
This page will not be added after purchasing Win2PDF.