



This Service Information bulletin supersedes SI M62 04 07 **dated April 2011**.

NEW designates changes to this revision

SUBJECT

Slight Buzzing Noise from Speedometer

MODEL

R55 (Cooper Clubman, Cooper S Clubman) with Navigation (SA609)

R56 (Cooper, Cooper S) with Navigation (SA609), vehicles produced from August 31, 2006

R57 (Cooper Convertible, Cooper S Convertible) with Navigation (SA609)

NEW R58 (Cooper Coupe, Cooper S Coupe, John Cooper Works Cooper Coupe) with Champ2/Business Navigation (SA606) or Champ2/Visual Boost (SA6FP)

NEW R59 (Cooper Roadster, Cooper S Roadster, John Cooper Works Roadster) with Champ2/Business Navigation (SA606) or Champ2/Visual Boost (SA6FP)

R60 (Cooper Countryman, Cooper S Countryman, Cooper S Countryman All4) with Champ2/Business Navigation (SA606) or Champ2/Visual Boost (SA6FP)

SITUATION

NEW When the vehicle is decelerating, the customer might experience a slight buzzing noise from the speedometer when the speedometer needle is between 0 and 12 miles per hour.

GENERAL INFORMATION

This is normal operation. Any attempt to rectify this complaint, either by parts replacement or coding, is not possible.

WARRANTY INFORMATION

Not applicable

[MINI, a division of BMW of North America, LLC
Copyright © 2012 BMW of North America, LLC]