

Error Memory

Date: 1/7/21 6:22:13 PM
VIN: WMWSV3C52DT477145

Junction Box Electronics

4 errors

A86D: HECKSCHEIBENHEIZUNG_RELAIS_DEFEKT_ODER_LEITUNG_ZUR_HECKSCHEIBE_UNTERBRUCHEN
C914: PT_CAN_ID2A6_BEDIENUNG_WISCHER_TIMEOUT
C913: LIN_KOMMUNIKATION
A86E: UNDERVOLTAGE

Crash Safety Module

1 error

93D2: Passenger Airbag Off Light (POL)

Engine Electronics

9 errors

3BCC: 0x3BCC PT-CAN, message (heat flux / load moment climate, 0x1B5): missing
3BD5: 0x3BD5 PT-CAN, message (status DSC, 0x19E): missing
3BD7: 0x3BD7 PT-CAN, message (speed, 0x1A0): missing
3BD2: 0x3BD2 PT-CAN, message (wheel speed, 0xCE): missing
3BD1: 0x3BD1 PT-CAN, message (torque request DSC, 0x0B6): missing
3BED: 0x3BED PT-CAN, message (cruise control, 0x194): missing
2C0F: 0x2C0F Fuel pump relay, control: Short circuit to earth
387F: 0x387F power management, quiescent current monitoring: closed circuit current violation
387C: 0x387C power management, battery monitoring: deep discharge

Electronic Power Steering

2 errors

D514: [CAN]: Speed signal, Id 1A0h, No message

D516: [CAN]: Steering angle, Id C4h, No message

Car Access System

2 errors

A0B5: Signalerkennung_Geschwindigkeit_Fehler

A0B2: Fehler_CAS_Versorgung

Instrument Cluster

7 errors

A3B9: CAN_ID_19E_ERROR_Failure_Message_Status_DSC

A3C3: RDC_Failure_NETWORKMANAGMENT

A3AC: CAN_ID_1A6_ERROR_Failure_Message_stretch of way

A550: ID_Failure 1A0h speed

A3A9: CAN_ID_1EE_ERROR_Failure_Message_LSS

A559: KL30g_f cutoff

A567: ID_Failure drop-arm switch

Bmw Professional Radio

1 error

ABEB: 0xABEB: Error in the connection diversity to the antennas

Driver's Side Footwell Module

2 errors

9CB5: Deep discharge battery

E594: Telegram steering angle timeout