

Safety Recall
24V-104
Integrated Brake (IB)
Model Year 2025
MINI Hardtop Cooper (2 Door, 4 Door)
MINI Cooper Countryman
Issue Date: 08/09/2024

Q1. Which MINI models in the US are potentially affected by this Safety Recall?

Certain Model Year 2025 MINI Hardtop Cooper (2 Door, 4 Door), and MINI Cooper Countryman models, in the US are potentially affected.

Q2. What is the specific issue?

The Integrated Brake (IB) module may not function according to specifications. If this happens, a warning lamp and message will be displayed in the instrument cluster. There will be a reduction in power assist braking, which could lead to an extended stopping distance and increase the risk of a crash. The Antilock Brake System (ABS) and Dynamic Stability Control (DSC) system may also not function, which could affect vehicle handling and control. Please note that higher pedal force may be required.

However, fully mechanical braking is not affected. If the IB module is not functioning properly, the parking (emergency) brake will be automatically activated to aid in braking performance. Also, the emergency function of the brake force distribution system remains available to help maintain vehicle stability and control.

If you notice any of these conditions, your vehicle may be experiencing this issue. Please drive carefully, and avoid abrupt braking as much as possible. Please contact an authorized MINI dealer as soon as possible to have the vehicle remedied.

If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

Q3. Why are other models / vehicles not included in this Safety Recall?

Other models have an Integrated Brake (IB) system that was produced to specifications by the supplier.

Q4. Can I continue to drive my vehicle?

Yes. However, when you are notified by MINI of this Safety Recall that a remedy is available, please contact an authorized MINI dealer to schedule an appointment as soon as possible. For the latest updates to this Safety Recall, please visit miniusa.com/recall. **If you are not the only driver of this vehicle, please advise all other drivers of this important information.**

Q5. How did MINI become aware of the issue?

MINI became aware of the issue through its quality control procedures.

Q6. How will I be informed of this Safety Recall?

Owners of potentially affected vehicles will be notified via First Class mail advising them of this Safety Recall. When parts become available, they will receive another letter, requesting that they schedule an appointment with an authorized MINI dealer as soon as possible to have this Safety Recall performed. For the latest updates to this Safety Recall, please visit miniusa.com/recall.

To ensure MINI has the most up-to-date contact and vehicle information, owners should register their vehicle at miniusa.com/ol. Registration is free and will give them access to other information specific for their MINI vehicle. Alternatively, owners can visit miniusa.com/recall and click on “**Manage recall notices and contact information**”.

Q7. How will my vehicle be remedied?

When the remedy is available, potentially affected vehicles will have the Integrated Brake (IB) system replaced for free which should take several hours.

Q8. Do I have to wait for MINI to contact me to have the remedy performed?

Yes. We are in the process of implementing this Safety Recall to ensure that the necessary parts, tools, and procedures are available. For the latest updates to this recall, please visit miniusa.com/recall.