



File name: UPD01006.bin

Content

The content of the software update depends on the status of the software installed in your vehicle. See the description below for details of the possible content of the update and the devices supported.

From those listed below, the version that is appropriate for your vehicle is installed:

- MX-3.5.4, TX-3.5.6
- TX-2.6.6

Conditions

The software update is available only for certain vehicles equipped with a USB audio interface. In these vehicles, the main menu 'Settings' includes the menu item 'Software update'. Further information is provided in the MINI Connected Owner's Handbook under 'Software update'.

Go to www.mini.com/connectivity to find out whether your vehicle is supported and compatible.

The software update is relevant for the following option combinations:

- SA6FP+6NE (Radio MINI Visual Boost + Mobile Bluetooth Preparation with USB-Audio-Interface)
- SA6UM+6NE (MINI Navigation System + Mobile Bluetooth Preparation with USB-Audio-Interface)
- SA7L5 (Wired)

Installation

Installation of the software update requires agreement with the terms and conditions of use. For more information, see www.mini.com/connectivity. For the purposes of installation, save the software update file in the main directory of a USB drive. Observe the additional instructions in the MINI Connected Owner's Handbook under 'Software update'. Following installation of the software update, the new software status is shown in the vehicle under 'Show current version'.

Notes

Once the software has been updated, the software in the vehicle is restarted and data transferred from the USB drive resynchronised where necessary. Wait a few minutes until the USB drive is operational again. Tracks or playlists played before the software update must be selected again. This is also necessary if the previous version of the software is restored using 'Restore previous version'.

Software update (MX-3.5.4, TX-3.5.6)

Content

- Office: Improved support for email messages.
- Telephone: Improved USB connection for iPhone devices with iOS 5. Improved connectivity of certain devices. For certain devices, better display and stability during calls. Improved Bluetooth connection with HTC devices. Improved sorting of the phone book in Android devices in Japan.
- Multimedia: Improved display of additional album and track information. Better connectivity for Bluetooth audio devices.

Supported devices

The software update improves the compatibility of the following devices:

Multimedia

- All USB devices
- Apple: iPod touch, iPhone
- Archos: 3 Vision
- Creative: MuVo V100
- Iriver: E100
- Palm: Pre
- Sony Ericsson: C905
- Symbian Foundations: S60
- Yari: U200



Phone

- Apple: iPhone 3GS, 4, 4S, 5 (iOS 5, iOS 6)
- Blackberry (OS 6.x), Pearl, 9800, 9900
- DoCoMo: Galaxy S SC-02B, NEC MEDIAS N-04C, Samsung Galaxy S II SC-02C, Sharp Aquos Phone SH-12C, Xperia Acro SO-02C, Xperia Arc SO-01C
- HTC: Sensation, Trinity
- LG: Enlighten VS700
- Motorola: DROID RAZR 4G
- Nokia: C7, N8, X7
- Samsung: Galaxy S II (Android 2.3.3), Nexus S
- Sharp: au IS03
- Sony Ericsson: W205
- Verizon Wireless: Casio C781, ZTE F450, Pantech 8992

Notes

Following installation of the software update, the following software status is shown in the vehicle under 'Show current version':

- MX-3.5.4
- TX-3.5.6

Software update (TX-2.6.6)

Content

- Office: Improved support for email messages.
- Telephone: Improved connection setup with certain devices. For certain devices, better display and stability during calls. Improved Bluetooth connection with HTC devices.

Support devices

The software update improves the compatibility of the following devices:

Phone

- Apple: iPhone 3GS, 4, 4S, 5 (iOS 5, iOS 6)
- Blackberry (OS 6.x), Pearl, 9800, 9900
- DoCoMo: Galaxy S SC-02B, NEC MEDIAS N-04C, Samsung Galaxy S II SC-02C, Sharp Aquos phone SH-12C, Xperia Acro SO-02C, Xperia Arc SO-01C
- HTC: Sensation, Trinity
- LG: Enlighten VS700
- Motorola: DROID RAZR 4G
- Nokia: C7, N8, X7
- Samsung: Galaxy S II (Android 2.3.3), Nexus S
- Sharp: au IS03
- Sony Ericsson: W205
- Verizon Wireless: Casio C781, ZTE F450, Pantech 8992

Notes

Following installation of the software update, the following software status is shown in the vehicle under 'Show current version':

- TX-2.6.6