





MINI : R53 Hardtop (2003) : Cooper S : -11/2004 (with Non-Adjustable Rear Camber) : 17" Wheel ExpressAlign Total Alignment



rotated J will cause pull right

max a d J



• One or more values are not within specification. Tire wear, handling and safety problems may result.