


Front end of latching hook actuator rod



Aft end of latching hook actuator rod



Passenger side: second plastic tab on top of aft end of actuator rod is broken off