

IDENTIFICATION READ

Datum : 16.11.2025 09:53:42
Baureihe : R50

Control unit : Body and Lights redesign
SGBD : bc1rd
JobStatus : OKAY
BMW part number : 6982115
Hardware number : 15
Software number : 44
Supplier : Reinshagen => Delphi
Support-Nr : 1
Coding index : 7
Diagnostic index : A3
Bus index : 14
Creating date CW/Year : 21/8

Control unit : Engine Management
SGBD : ems2k
JobStatus : IFH-0009: NO RESPONSE FROM CONTROLUNIT

Control unit : Airbag
SGBD : mrs4
JobStatus : IFH-0009: NO RESPONSE FROM CONTROLUNIT

Control unit : ABS / DSC
SGBD : dsc_mk60
JobStatus : IFH-0009: NO RESPONSE FROM CONTROLUNIT

Control unit : Immobiliser
SGBD : ews3
JobStatus : IFH-0009: NO RESPONSE FROM CONTROLUNIT

Control unit : Sunroof
SGBD : shd46
JobStatus : IFH-0009: NO RESPONSE FROM CONTROLUNIT

Control unit : Parking Aid
SGBD : pdcact
JobStatus : IFH-0009: NO RESPONSE FROM CONTROLUNIT

Control unit : Automatic Temp.Control
SGBD : ihkar50
JobStatus : IFH-0009: NO RESPONSE FROM CONTROLUNIT

Control unit : Instrument Pack
SGBD : kombi50f
JobStatus : OKAY
BMW part number : 9126996
Hardware number : 30
Software number : 24
Supplier : UK-NSI
Support-Nr : 35
Coding index : 11
Diagnostic index : 89
Bus index : 18
Creating date CW/Year : 23/8

Control unit : Instrument Remote
SGBD : rip
JobStatus : OKAY
BMW part number : 6966499
Hardware number : 11
Software number : 21
Supplier : UK-NSI

Support-Nr : 35
Coding index : 4
Diagnostic index : 89
Bus index : 18
Creating date CW/Year : 22/8

Control unit : Power Steering
SGBD : ehpsr50
JobStatus : IFH-0009: NO RESPONSE FROM CONTROLUNIT

Control unit : Navigation Europe
SGBD : navmk3
JobStatus : IFH-0009: NO RESPONSE FROM CONTROLUNIT

Control unit : Navigation Japan
SGBD : nav_jap
JobStatus : IFH-0009: NO RESPONSE FROM CONTROLUNIT

Control unit : TV / Video Module
SGBD : videomod
JobStatus : IFH-0009: NO RESPONSE FROM CONTROLUNIT

Control unit : BMBT / Display & Controls
SGBD : bmbtr50
JobStatus : IFH-0009: NO RESPONSE FROM CONTROLUNIT

Control unit : MFL Steering Switches
SGBD : mflr50
JobStatus : IFH-0009: NO RESPONSE FROM CONTROLUNIT

Control unit : DWS / Tyre Pressure
SGBD : dws
JobStatus : IFH-0009: NO RESPONSE FROM CONTROLUNIT

Control unit : Radio
SGBD : radio
JobStatus : IFH-0009: NO RESPONSE FROM CONTROLUNIT

Control unit : Rain Sensor
SGBD : rls_ds2
JobStatus : IFH-0009: NO RESPONSE FROM CONTROLUNIT

Control unit : Headlamp
SGBD : lwr2a
JobStatus : IFH-0009: NO RESPONSE FROM CONTROLUNIT

Control unit : Steering Angle Sensor
SGBD : lws5_1b
JobStatus : IFH-0009: NO RESPONSE FROM CONTROLUNIT

Control unit : Audio Amplifier
SGBD : dsp_r50
JobStatus : IFH-0009: NO RESPONSE FROM CONTROLUNIT
