



## Service Bulletins Summary

**Make / Models:**

MINI / COOPER

MINI / COOPER CLUBMAN

MINI / COOPER COUNTRYMAN

MINI / COOPER S

MINI / COOPER S CLUBMAN

MINI / COOPER S CONVERTIBLE

MINI / COOPER S COUNTRYMAN

MINI / COOPER S US

**Model/Build Years:**

2010-2011

2010-2011

2011-2012

2010-2012

2010-2011

2010-2011

2011

2011

---

**Service Bulletin Number:**

SIM-12-03-11

**NHTSA Item Number:**10043873

---

**Summary:**

MINI: SERVICE ENGINE SOON IS ILLUMINATED DUE TO TANK VENTILATION VALVE (TEV) BEING JAMMED OPEN AND FUEL CAP, WITH EVAPORATIVE SYSTEM LEAKAGE, WAS INCORRECTLY INSTALLED. \*PE

[Close Window](#)