


Remove cowl panel cover.



Release Nut (1).

*Install hint:*

Ensure bracket is located correct to grommet.

Remove screws (2).

*Install hint: (All fixings)*

Tightening Torque 61 61 2AZ.

Disconnect connector of motor and remove wiper mechanism/motor.