

VIN:XXXXXXXXVehicle:MINI/F56/HAT/Cooper/B38/AUTO/USA/LL/2014/11

System Version: 3.47.10.13054Data Version: R3.47.10.13054

51 45 180


Removing and installing (replacing)
lower left instrument panel trim



- Necessary preliminary tasks:
- Remove [side panel on dashboard, left](#)



REMOVAL:



- Unclip the bottom instrument panel trim cover (1) from retaining clips (2) and remove.
- Unlock associated plug connections and disconnect.
- Remove bottom instrument panel trim (1).




- Replacement:
- Remount [light operating facility](#).



INSTALLATION:

- Connect plug connections.
- Engage trim panel (1) in retaining clips (2).



Required reworking:

- Install [side panel on instrument panel, left](#)