

VIN:XXXXXXXXVehicle:MINI/F56/HAT/Cooper/B38/AUTO/USA/LL/2014/11


System Version: 3.47.10.13054Data Version: R3.47.10.13054

51 49 000

Removing and installing or replacing trim for rear lid



REMOVAL:



Remove warning triangle.


Release screws (1).

Remove warning triangle holder.

Release trim panel (4) from clips (2 and 3) and remove.



INSTALLATION:



*Note:*

Replace faulty clips (2 and 3).

Position and clip in trim panel (4) with clips (2 and 3).

Secure warning triangle holder with screws (1).

Install warning triangle.