

# Error memory

## Crash Safety Module

1 error

93C3: OC3

## Engine Electronics

10 errors

2B51: 0X2B51 AIR MASS METER, SIGNAL

2841: 0X2841 VANOS SOLENOID VALVE OUTLET, CONTROL

2878: 0X2878 VANOS SOLENOID VALVE INLET, CONTROL

27B2: 0X27B2 TANK VENT VALVE, CONTROL

2EE3: 0X2EE3 MAP THERMOSTAT, CONTROL

2A63: 0X2A63 LAMBDA PROBE HEATING IN FRONT OF CATALYST, ACTIVATION

2F57: 0X2F57 OIL PRESSURE CONTROL VALVE, CONTROL

2B5F: 0X2B5F AIR MASS METER, CORRECTION SIGNAL

296B: 0X296B EXHAUST CAMSHAFT SENSOR

2986: 0X2986 EXHAUST CAMSHAFT SENSOR

## **Tyre Pressure Monitor**

5 errors

6054: ERROR WHEEL SENSOR VL

6055: ERROR WHEEL SENSOR VR

6056: ERROR WHEEL SENSOR HL

6057: ERROR WHEEL SENSOR HR

D115: ERROR CAN TELEGRAM TIMEOUT STAT\_GANG\_RUECKWAERTS

## **Central Headunit And Multimedia Platform**

1 error

C587: FALLING ASLEEP FROM THE HEAD UNIT IS PREVENTED

## **Driver's Side Footwell Module**

3 errors

A8C1: REAR RUNNING LIGHT LEFT DEFECTIVE

A8BB: TAILLIGHT LEFT 2, R56: SIDE MARKER LIGHT LEFT FRONT, RIGHT REAR DEFECTIVE, E84: TAIL LIGHT / BRAKE LIGHT LEFT DEFECTIVE

A8AC: LIMITING LIGHT LEFT DEFECTIVE